




PHASE SHIFT CONTROL RC BASE USING SCR & TRIAC

MODEL - PWR14

This trainer has been designed with a view to provide practical and experimental knowledge of Phase shift control R-C base using SCR & TRIAC.



SPECIFICATIONS

1. Power supply requirement : 230V AC, 50 Hz.
2. Following parts provided on Single PCB with connecting terminals.
Diac - DB3 - 1 No.
Triac - BT136 - 1 No.
100K Ohm Variable Resistor (Potentiometer)
SCR - Bt151- 1No.
22K ohm Variable Resistor (Potentiometer)
3. Standard Accessories :
 1. A Training Manual
 2. Connecting Patch cords.

In keeping view of SIGMA policy of continuous development and improvement, the Specifications may be changed without prior notice or obligation.

Sigma Trainers and Kits
E-113, Jai Ambe Nagar,
Near Udgam School,
Thaltej,
AHMEDABAD - 380054.
INDIA.

Phone(O): +91-79-26852427/ 26850829
Phone(F): +91-79-26767512/ 26767648
Fax : +91-79-26840290/ 26840290
Mobile : +91-9824001168
Email : sales@sigmatrainers.com
: sigmatrainers@sify.com
Web : www.sigmatrainers.com

Dealer:-