
## THREE PHASE HALF WAVE RECTIFIER MODEL-RECTO4

This trainer has been designed with a view to provide practical and experimental knowledge of ThreePhaseHalfwaveRectifier.



## SPECIFICATIONS

- 1. Power supply requirement : 440V AC, 3 Phase.
- 2. Following parts provided on Single PCB with connecting terminals.
- SCR : 3 Nos.
  - Load Resistors : 1K 10W, 1K 10W with 100mh Coil

:

- 3. Three Mains Transformer with step down AC Voltages : 0-30V/250 mA.
- 4. Accessories

A Training Manual

Connecting patch cords

In keeping view of SIGMA policy of continuous development and improvement, the Specifications may be changed without prior notice or obligation.